



深圳市诚锦鹏实业有限公司
SHENZHEN CHENGJINPENG INDUSTRIAL CO., LTD

无损检测报告

NONDESTRUCTIVE TESTING REPORT

工程名称 Project Name: HYSY115FPSO 气量超限改造工程

管道电仪保温类改造人员机具服务

HYSY115FPSO Gas Excess Reform Project Pipeline Electrical Instrument

Thermal Insulation Retrofit Personnel and Machinery Services

委托单位 Commission Unit : 深圳市海基实业有限公司

委托单位地址 Client Address: 深圳市南山区南海大道新能源大厦 A 座 11B10 室

工程编号 Project No. : CJP-WR-094-030-19-052

检测方法 Inspection Method : MT

报告编号 Report No. : CJP-WR-094-030-MT003-19-052

页数 Number of pages : 共 21 页

报告日期 Report Date : 2019.09.27

批准人 Approved by : [Signature]

检测单位: 深圳市诚锦鹏实业有限公司

CONTRACTOR: SHENZHEN CHENGJINPENG INDUSTRIAL CO.,LTD

地 址: 深圳市南山区月亮湾大道 2076 号高科大厦六层 C3

ADDRESS: C3F6, GAOKE BUILDING, NO.2076, YUELIANGWAN BLVD, NANSHAN DISTRICT, SHENZHEN

电 话 Tel: 0755-86274981/26440278

URL: <http://www.cjpsz.com> E-mail: cjpsz126@126.com



深圳市诚锦鹏实业有限公司
SHENZHEN CHENGJINPENG INDUSTRIAL CO.,LTD

磁粉检测报告
MAGNETIC PARTICLE INSPECTION REPORT

项目名称: HYSY115FPSO气量超限改造工程管道电仪保温类改造人员机具服务

报告日期

报告编号

Project Name:HYSY115FPSO Gas Excess Reform Project Pipeline Electrical Instrument Thermal Insulation Retrofit Personnel and Machinery Services

Report Date: 2019.09.27

Report No.:CJP-WR-094-030-MT003-19-052

检测地点 Testing Position	HYSY115	执行标准 Executive Standard	API-1104	仪器型号 Instrument Type	ZCM-AD22012	提升力 Lifting Power	≥45N		
检测比例 Testing Rate	100%	合格级别 Acceptance Grade	--	仪器编号 Instrument No.	CJP-CF-20	磁粉 Magnetic Particle	MT-BW		
图纸号 Drawing No.	--	表面状态 Surface Condition	Smooth	磁轭类型 Yoke Type	AC-Yoke	反差剂 Contrast Agent	FA-5		
工件材质 Workpiece Material	A106	灵敏度试块 Sensitivity block	A1(30/100)	磁化方法 Magnetizing Method	Successive	磁化时间 Magnetizing Time	1~3s		
工件编号 Workpiece No.	焊工号 Welder No.	焊口号 Weld No.	热处理状态	坡口形式	焊接方法 Welding Process	焊缝长度 W.L(mm)	缺陷编号 Defect No.	缺陷性质及大小 DNS	评定意见 Judge
2"-N2-38222-A2BZ	W35	80	--	V	GTAW	188	--	--	Acc
2"-N2-38222-A2BZ	W35	80A	--	V	GTAW	188	--	--	Acc
2"-N2-38222-A2BZ	W35	81	--	V	GTAW	188	--	--	Acc
2"-N2-38222-A2BZ	W35	81A	--	V	GTAW	188	--	--	Acc
2"-N2-38222-A2BZ	W35	81B	--	V	GTAW	188	--	--	Acc
2"-N2-38222-A2BZ	W35	82	--	V	GTAW	188	--	--	Acc
2"-N2-38222-A2BZ	W35	83	--	V	GTAW	188	--	--	Acc
2"-N2-38222-A2BZ	W35	85	--	V	GTAW	188	--	--	Acc
2"-N2-38222-A2BZ	W35	85A	--	V	GTAW	188	--	--	Acc
2"-N2-38222-A2BZ	W35	85B	--	V	GTAW	188	--	--	Acc
2"-N2-38222-A2BZ	W35	85C	--	V	GTAW	188	--	--	Acc
4"-CR-20043-A2BZ-HT45	W36	1	--	V	GTAW	356	--	--	Acc
备注:热处理状态(HTS--Heat Treatment State) Notes:缺陷性质及大小 (DNS--Defect Nature and Size)				未熔合(LOF--Lack of Fusion) 未焊透(LOP--Lack of Penetration) 夹渣(S.I--Slag Inclusion) 裂纹(C--Crack) 气孔(P--Porosity) 合格(Acc--Acceptance) 不合格(Rej-Rejection)					
签字 Signature		检验员 (Inspector)		技术监督(Tech. Supervisor)		签字授权人(Authorized Signee)			
日期 Date		2019.09.27		2019.09.27		2019.09.27			



磁粉检测报告 (续表)
MAGNETIC PARTICLE INSPECTION REPORT

项目名称:HYSY115FPSO气量超限改造工程管道电仪保温类改造人员机具服务

报告日期

报告编号

Project Name:HYSY115FPSO Gas Excess Reform Project Pipeline Electrical
Instrument Thermal Insulation Retrofit Personnel and Machinery Services

Report Date:2019.09.27

Report No.:CJP-WR-094-030-MT003-19-052

工件编号 Workpiece No.	焊工号 Welder No.	焊口号 Weld No.	热处理状态	坡口形式	焊接方法 Welding Process	焊缝长度 W.L(mm)	缺陷编号 Defect No.	缺陷性质及大小 DNS	评定意见 Judge
4"-CR-20043-A2BZ-HT45	W36	4	--	V	GTAW	356	--	--	Acc
4"-CR-20043-A2BZ-HT45	W36	10	--	V	GTAW	356	--	--	Acc
4"-CR-20043-A2BZ-HT45	W36	12	--	V	GTAW	356	--	--	Acc
4"-CR-20043-A2BZ-HT45	W36	13	--	V	GTAW	356	--	--	Acc
4"-CR-20043-A2BZ-HT45	W36	15	--	V	GTAW	356	--	--	Acc
4"-CR-20043-A2BZ-HT45	W36	16	--	V	GTAW	356	--	--	Acc
4"-DC-66235-A2BZ-HT45	W36	1	--	V	GTAW	356	--	--	Acc
4"-DC-66235-A2BZ-HT45	W36	2	--	V	GTAW	356	--	--	Acc
4"-DC-66235-A2BZ-HT45	W36	3	--	V	GTAW	356	--	--	Acc
4"-DC-66235-A2BZ-HT45	W36	205	--	V	GTAW	356	--	--	Acc
4"-DC-66235-A2BZ-HT45	W36	206	--	V	GTAW	356	--	--	Acc
4"-DC-66235-A2BZ-HT45	W36	207	--	V	GTAW	356	--	--	Acc
4"-DC-66235-A2BZ-HT45	W36	208	--	V	GTAW	356	--	--	Acc
4"-DC-66235-A2BZ-HT45	W36	209	--	V	GTAW	356	--	--	Acc
4"-DC-66235-A2BZ-HT45	W36	211	--	V	GTAW	356	--	--	Acc
8"-AG-20002-A2BZ-P	W37	97A	--	V	GTAW	688	--	--	Acc
8"-AG-20002-A2BZ-P	W37	97B	--	V	GTAW	688	--	--	Acc
8"-AG-20002-A2BZ-P	W37	97C	--	V	GTAW	688	--	--	Acc
8"-AG-20002-A2BZ-P	W37	97D	--	V	GTAW	688	--	--	Acc
8"-AG-20002-A2BZ-P	HJ130006	99A	--	V	GTAW	688	--	--	Acc

备注:热处理状态(HTS--Heat Treatment State)

Notes:缺陷性质及大小 (DNS--Defect Nature and Size)

未熔合 (LOF--Lack of Fusion) 未焊透 (LOP--Lack of Penetration) 夹渣 (S.I--Slag Inclusion)
裂纹 (C--Crack) 气孔 (P--Porosity) 合格 (Acc--Acceptance) 不合格 (Rej--Rejection)

签字 Sign	检验员 (Inspector) Ou Baoyi	技术监督 (Tech. Supervisor) Tang Yuzhu	签字授权人 (Authorized Signee) 2019.09.27
日期 Date	2019.09.27	2019.09.27	2019.09.27



深圳市诚锦鹏实业有限公司
SHENZHEN CHENGJINPENG INDUSTRIAL CO.,LTD

磁粉检测报告 (续表)

MAGNETIC PARTICLE INSPECTION REPORT

项目名称: HYSY115FPS0 气量超限改造工程管道电仪保温类改造人员机具服务

报告日期

报告编号

Project Name: HYSY115FPS0 Gas Excess Reform Project Pipeline Electrical
Instrument Thermal Insulation Retrofit Personnel and Machinery Services

Report Date: 2019.09.27

Report No.: CJP-WR-094-030-MT003-19-052

工件编号 Workpiece No.	焊工号 Welder No.	焊口号 Weld No.	热处理状态 HTS	坡口形式 C	焊接方法 Welding Process	焊缝长度 W.L (mm)	缺陷编号 Defect No.	缺陷性质及大小 DNS	评定意见 Judge
8"-AG-20002-A2BZ-H	W37	11	---	V	GTAW	688	---	---	Acc
8"-AG-20002-A2BZ-H	W37	13	---	V	GTAW	688	---	---	Acc
8"-AG-20002-A2BZ-P	W37	99	---	V	GTAW	688	---	---	Acc
8"-AG-20002-A2BZ-P	W37	99B	---	V	GTAW	688	---	---	Acc
8"-AG-20002-A2BZ-P	W37	100	---	V	GTAW	688	---	---	Acc
8"-HM-20156-B2BH-H	W35	374	---	V	GTAW	688	---	---	Acc
8"-HM-50150-B2BH-H	W35	376	---	V	GTAW	688	---	---	Acc
8"-HM-50150-B2BH-H	W35	377	---	V	GTAW	688	---	---	Acc
8"-HM-50150-B2BH-H	W35	380	---	V	GTAW	688	---	---	Acc
10"-CR-20058-A2BZ-HT45	W37	1	---	V	GTAW	857	---	---	Acc
10"-CR-20058-A2BZ-HT45	W37	2	---	V	GTAW	857	---	---	Acc
10"-CR-20058-A2BZ-HT45	W37	4	---	V	GTAW	857	---	---	Acc
10"-CR-20058-A2BZ-HT45	W37	5	---	V	GTAW	857	---	---	Acc
10"-CR-20058-A2BZ-HT45	W37	6	---	V	GTAW	857	---	---	Acc
10"-CR-20058-A2BZ-HT45	W37	7	---	V	GTAW	857	---	---	Acc
10"-CR-20058-A2BZ-HT45	W37	8	---	V	GTAW	857	---	---	Acc
10"-CR-20058-A2BZ-HT45	W37	9	---	V	GTAW	857	---	---	Acc
10"-CR-20058-A2BZ-HT45	W37	10	---	V	GTAW	857	---	---	Acc
10"-CR-20058-A2BZ-HT45	W37	11	---	V	GTAW	857	---	---	Acc
10"-CR-20058-A2BZ-HT45	W37	12	---	V	GTAW	857	---	---	Acc

备注: 热处理状态 (HTS--Heat Treatment State)

Notes: 缺陷性质及大小 (DNS--Defect Nature and Size)

未熔合 (LOF--Lack of Fusion) 未焊透 (LOP--Lack of Penetration) 夹渣 (S.I--Slag Inclusion)
裂纹 (C--Crack) 气孔 (P--Porosity) 合格 (Acc--Acceptance) 不合格 (Rej--Rejection)

签字 Sign	检验员 (Inspector) Ou Bang hua	技术监督 (Tech. Supervisor) Tang Wezu	签字授权人 (Authorized Signee) 2019.09.27
日期 Date	2019.09.27	2019.09.27	2019.09.27



深圳市诚锦鹏实业有限公司
SHENZHEN CHENGJINPENG INDUSTRIAL CO.,LTD

磁粉检测报告 (续表)

MAGNETIC PARTICLE INSPECTION REPORT

项目名称: HYSY115FPSO 气量超限改造工程管道电仪保温类改造人员机具服务

报告日期

报告编号

Project Name: HYSY115FPSO Gas Excess Reform Project Pipeline Electrical
Instrument Thermal Insulation Retrofit Personnel and Machinery Services

Report Date: 2019.09.27

Report No.: CJP-WR-094-030-MT003-19-052

工件编号 Workpiece No.	焊工号 Welder No.	焊口号 Weld No.	热处理状态 HTS	坡口形式 Groove Form	焊接方法 Welding Process	焊缝长度 W.L (mm)	缺陷编号 Defect No.	缺陷性质及大小 DNS	评定意见 Judge
10"-CR-20058-A2BZ-HT45	W35	21A	--	V	GTAW	857	--	--	Acc
10"-CR-20059-A2BZ-HT45	W37	1	--	V	GTAW	857	--	--	Acc
10"-CR-20059-A2BZ-HT45	W37	4	--	V	GTAW	857	--	--	Acc
10"-CR-20059-A2BZ-HT45	W37	5	--	V	GTAW	857	--	--	Acc
10"-CR-20059-A2BZ-HT45	W37	6	--	V	GTAW	857	--	--	Acc
10"-CR-20059-A2BZ-HT45	W37	7	--	V	GTAW	857	--	--	Acc
10"-CR-20059-A2BZ-HT45	W37	8	--	V	GTAW	857	--	--	Acc
10"-CR-20059-A2BZ-HT45	W37	9	--	V	GTAW	857	--	--	Acc
10"-CR-20059-A2BZ-HT45	W37	9A	--	V	GTAW	857	--	--	Acc
10"-CR-20059-A2BZ-HT45	W37	9B	--	V	GTAW	857	--	--	Acc
10"-CR-20059-A2BZ-HT45	W37	9D	--	V	GTAW	857	--	--	Acc
10"-CR-20059-A2BZ-HT45	W37	19A	--	V	GTAW	857	--	--	Acc
10"-CR-20060-A2BZ-HT45	W37	1	--	V	GTAW	857	--	--	Acc
10"-CR-20060-A2BZ-HT45	W37	4	--	V	GTAW	857	--	--	Acc
10"-CR-20060-A2BZ-HT45	W37	5	--	V	GTAW	857	--	--	Acc
10"-CR-20060-A2BZ-HT45	W37	6	--	V	GTAW	857	--	--	Acc
10"-CR-20060-A2BZ-HT45	W37	7	--	V	GTAW	857	--	--	Acc
10"-CR-20060-A2BZ-HT45	W37	8	--	V	GTAW	857	--	--	Acc
10"-CR-20060-A2BZ-HT45	W37	9	--	V	GTAW	857	--	--	Acc
10"-CR-20060-A2BZ-HT45	W37	16	--	V	GTAW	857	--	--	Acc

备注: 热处理状态 (HTS--Heat Treatment State) 未熔合 (LOF--Lack of Fusion) 未焊透 (LOP--Lack of Penetration) 夹渣 (S.I--Slag Inclusion)
Notes: 缺陷性质及大小 (DNS--Defect Nature and Size) 裂纹 (C--Crack) 气孔 (P--Porosity) 合格 (Acc--Acceptance) 不合格 (Rej--Rejection)

签字 Sign	检验员 (Inspector) Du Bang hua	技术监督 (Tech. Supervisor) Tang Yue zu	签字授权人 (Authorized Signee)
日期 Date	2019.09.27	2019.09.27	2019.09.27



深圳市诚锦鹏实业有限公司
SHENZHEN CHENGJINPENG INDUSTRIAL CO.,LTD

磁粉检测报告 (续表)

MAGNETIC PARTICLE INSPECTION REPORT

项目名称: HYSY115FPSO 气量超限改造工程管道电仪保温类改造人员机具服务

报告日期

报告编号

Project Name: HYSY115FPSO Gas Excess Reform Project Pipeline Electrical
Instrument Thermal Insulation Retrofit Personnel and Machinery Services

Report Date: 2019.09.27

Report No.: CJP-WR-094-030-MT003-19-052

工件编号 Workpiece No.	焊工号 Welder No.	焊口号 Weld No.	热处理状态	坡口形式	焊接方法 Welding Process	焊缝长度 W. L (mm)	缺陷编号 Defect No.	缺陷性质及大小 DNS	评定意见 Judge
10"-CR-20060-A2BZ-HT45	W37	21	--	V	GTAW	857	--	--	Acc
10"-CR-20335-A2BZ-HT45	W37	1	--	V	GTAW	857	--	--	Acc
10"-CR-20335-A2BZ-HT45	W37	3	--	V	GTAW	857	--	--	Acc
10"-CR-20335-A2BZ-HT45	W37	4	--	V	GTAW	857	--	--	Acc
10"-CR-20335-A2BZ-HT45	W37	6	--	V	GTAW	857	--	--	Acc
10"-CR-20335-A2BZ-HT45	W37	13	--	V	GTAW	857	--	--	Acc
10"-PW-30101-A2BZ-P	W37	1	--	V	GTAW	857	--	--	Acc
10"-PW-30101-A2BZ-P	W37	2	--	V	GTAW	857	--	--	Acc
10"-PW-30101-A2BZ-P	W37	6	--	V	GTAW	857	--	--	Acc
10"-PW-30101-A2BZ-P	W37	7	--	V	GTAW	857	--	--	Acc
10"-PW-30101-A2BZ-P	HJ130006	9	--	V	GTAW	857	--	--	Acc
10"-PW-30101-A2BZ-P	W37	12	--	V	GTAW	857	--	--	Acc
10"-PW-30101-A2BZ-P	W37	13	--	V	GTAW	857	--	--	Acc
10"-PW-30101-A2BZ-P	W37	17	--	V	GTAW	857	--	--	Acc
10"-PW-30101-A2BZ-P	W37	18	--	V	GTAW	857	--	--	Acc
10"-PW-30101-A2BZ-P	W37	21	--	V	GTAW	857	--	--	Acc
14"-CR-20170-A2BZ-HT45	W37	249D	--	V	GTAW	1118	--	--	Acc
14"-CR-20170-A2BZ-HT45	W37	251A	--	V	GTAW	1118	--	--	Acc
14"-CR-20170-A2BZ-HT45	W37	248	--	V	GTAW	1118	--	--	Acc
14"-CR-20170-A2BZ-HT45	W37	249	--	V	GTAW	1118	--	--	Acc

备注: 热处理状态 (HTS--Heat Treatment State)

Notes: 缺陷性质及大小 (DNS--Defect Nature and Size)

未熔合 (LOF--Lack of Fusion) 未焊透 (LOP--Lack of Penetration) 夹渣 (S.I--Slag Inclusion)

裂纹 (C--Crack) 气孔 (P--Porosity) 合格 (Acc--Acceptance) 不合格 (Rej--Rejection)

签字 Sign	检验员 (Inspector)	技术监督 (Tech. Supervisor)	签字授权人 (Authorized Signee)
日期 Date	Ou Bang hua 2019.09.27	Tang Xuewu 2019.09.27	2019.09.27



深圳市诚锦鹏实业有限公司
SHENZHEN CHENGJINPENG INDUSTRIAL CO.,LTD

磁粉检测报告 (续表)
MAGNETIC PARTICLE INSPECTION REPORT

项目名称: HYSY115FPSO 气量超限改造工程管道电仪保温类改造人员机具服务

报告日期

报告编号

Project Name: HYSY115FPSO Gas Excess Reform Project Pipeline Electrical
Instrument Thermal Insulation Retrofit Personnel and Machinery Services

Report Date: 2019.09.27

Report No.: CJP-WR-094-030-MT003-19-052

工件编号 Workpiece No.	焊工号 Welder No.	焊口号 Weld No.	热处理状态	坡口形式	焊接方法 Welding Process	焊缝长度 W. L (mm)	缺陷编号 Defect No.	缺陷性质及大小 DNS	评定意见 Judge
14"-CR-20170-A2BZ-HT45	W37	249A	--	V	GTAW	1118	--	--	Acc
14"-CR-20170-A2BZ-HT45	W37	249B	--	V	GTAW	1118	--	--	Acc
14"-CR-20170-A2BZ-HT45	W36	249C	--	V	GTAW	1118	--	--	Acc
14"-CR-20170-A2BZ-HT45	W37	249E	--	V	GTAW	1118	--	--	Acc
14"-CR-20170-A2BZ-HT45	W37	249F	--	V	GTAW	1118	--	--	Acc
14"-CR-20170-A2BZ-HT45	W37	250	--	V	GTAW	1118	--	--	Acc
16"-CR-20005-A2BZ-HT45	W35	9	--	V	GTAW	1275	--	--	Acc
16"-CR-20005-A2BZ-HT45	W35	10	--	V	GTAW	1275	--	--	Acc
16"-CR-20005-A2BZ-HT45	W35	11	--	V	GTAW	1275	--	--	Acc
16"-CR-20005-A2BZ-HT45	W35	11A	--	V	GTAW	1275	--	--	Acc
16"-CR-20005-A2BZ-HT45	W35	12	--	V	GTAW	1275	--	--	Acc
16"-CR-20005-A2BZ-HT45	HJ130006	13	--	V	GTAW	1275	--	--	Acc
16"-CR-20005-A2BZ-HT45	W35	13A	--	V	GTAW	1275	--	--	Acc
16"-CR-20005-A2BZ-HT45	W35	14	--	V	GTAW	1275	--	--	Acc
16"-CR-20005-A2BZ-HT45	W35	15	--	V	GTAW	1275	--	--	Acc
16"-CR-20005-A2BZ-HT45	W35	16	--	V	GTAW	1275	--	--	Acc
16"-CR-20005-A2BZ-HT45	W35	17	--	V	GTAW	1275	--	--	Acc
16"-CR-20005-A2BZ-HT45	W35	18	--	V	GTAW	1275	--	--	Acc
16"-CR-20005-A2BZ-HT45	W35	19	--	V	GTAW	1275	--	--	Acc
16"-CR-20005-A2BZ-HT45	W35	21	--	V	GTAW	1275	--	--	Acc
备注: 热处理状态 (HTS--Heat Treatment State) Notes: 缺陷性质及大小 (DNS--Defect Nature and Size)				未熔合 (LOF--Lack of Fusion) 未焊透 (LOP--Lack of Penetration) 夹渣 (S.I--Slag Inclusion) 裂纹 (C--Crack) 气孔 (P--Porosity) 合格 (Acc--Acceptance) 不合格 (Rej--Rejection)					
签字 Sign		检验员 (Inspector)			技术监督 (Tech. Supervisor)		签字授权人 (Authorized Signee)		
日期 Date		Ou Bang Hua 2019.09.27			Tang Xuewen 2019.09.27		2019.09.27		



MAGNETIC PARTICLE INSPECTION REPORT

报告编号

Report No. :CJP-WR-094-030-MT003-19-052

Form No: CJP/WR. MT02 Rev: E/0

检测报告附图
SKETCH OF DETECTION POSITION

报告编号:

Report No: CJP-WR-094-030-MT003-19-052




2 " -38222-80



2 " -38222-80B



2 " -38222-81A



2-38222-81B



2-38222- 82 83



2-38222-85 85A



2-38222-85B 85C



4-20043-1



4-20043-4

检测报告附图 SKETCH OF DETECTION POSITION

报告编号:
Report No: CJP-WR-094-030-MT003-19-052



4-20043-10



4-20043-12



4-20043-13



4-20043-15



4-20043-16



4-66235- 3



4-66235-1 2



4-66235-205 / 206




4-66235-207

检测报告附图
SKETCH OF DETECTION POSITION

报告编号:
Report No: CJP-WR-094-030-MT003-19-052



4-66235-208



4-66235-209



4-66235-211



8-20002- 97A/ 97B/ 97C



8-20002- 99A



8-20002-11



8-20002-13



8-20002-97D



8-20002-99

检测报告附图
SKETCH OF DETECTION POSITION

报告编号:

Report No: CJP-WR-094-030-MT003-19-052



8-20002-99B




8-20002-100



8-20156-374



8-50150-376



8-50150-377



8-50150-380



10-20058-1



10-20058-2



10-20058-4

检测报告附图
SKETCH OF DETECTION POSITION

报告编号:

Report No: CJP-WR-094-030-MT003-19-052




10-20058-5



10-20058-6



10-20058-7 / 8



10-20058-9



10-20058-10



10-20058-11



10-20058-12



10-20058-21A



10-20059-1

检测报告附图 SKETCH OF DETECTION POSITION

报告编号:

Report No: CJP-WR-094-030-MT003-19-052




10 " -20059-4



10 " -20059-5



10 " -20059-6



10 " -20059-7



10 " -20059-8



10 " -20059-9/9A/9B



10 " -20059-9D



10 " -20059-19A




10 " -20060-1

检测报告附图
SKETCH OF DETECTION POSITION

报告编号:


Report No: CJP-WR-094-030-MT003-19-052



10-20060-4



10-20060-5



10-20060-6



10-20060-7



10-20060-8



10-20060-9



10-20060-16



10-20060-21



10-20354-1

检测报告附图 SKETCH OF DETECTION POSITION

报告编号:
Report No: CJP-WR-094-030-MT003-19-052



10-20354- 3 / 4



10-20354-6



10-20354-13



10-30101-1 2



10-30101-6




10-30101-7



10-30101-9



10-30101-12



10-30101-13

检测报告附图
SKETCH OF DETECTION POSITION

报告编号:


Report No: CJP-WR-094-030-MT003-19-052



10-30101-17 18




10-30101-21



14-20170- 249D




14-20170- 251A



14-20170-248



14-20170-249



14-20170-249A



14-20170-249B



14-20170-249C

检测报告附图 SKETCH OF DETECTION POSITION


报告编号:
Report No: CJP-WR-094-030-MT003-19-052



14-20170-249E



14-20170-249F




14-20170-250



16-20005-9




16-20005-10



16-20005-11



16-20005-11A



16-20005-12



16-20005-13

检测报告附图
SKETCH OF DETECTION POSITION


报告编号:
Report No: CJP-WR-094-030-MT003-19-052



16-20005-13A



16-20005-14




16-20005-15



16-20005-16



16-20005-17



16-20005-18



16-20005-19



16-20005-21



16-20005-23

检测报告附图
SKETCH OF DETECTION POSITION

报告编号:
Report No: CJP-WR-094-030-MT003-19-052




16-20005-13A



16-20005-14



16-20005-15



16-20005-16



16-20005-17



备注

Remark

1. 报告无检测单位“检测专用章”无效。

Report without the specified inspection stamp of CJP company is invalid.

2. 报告无操作人员或评片人、技术监督、技术负责人签字无效。

Report without the signatures of operator of film judge, tech. supervisor and tech. principal is invalid.

3. 本报告涂改无效。

Report with alteration will be invalid.

4. 本报告仅对被检产品受检部位负责。

Report is only responsible for the inspective pieces.

5. 未经检测单位同意不得复制本报告。

Report should not be copied without the agreement of CJP company.

6. 委托单位对检测结果若有异议，请于十五日内提出。

Client should inform CJP company within 15 days if there're any question about the inspective result.

7. 本报告一式三份；本公司存档一份，客户两份。

Report is in triplicity, original stored in CJP company, two copies for client.

8. 未加盖 CMA 章的检测报告，不具备向社会起证明作用的数据和结果。

The data and result of the inspection report that unsealed can not be proved to society.

检测单位：深圳市诚锦鹏实业有限公司

Contractor: Shenzhen Chengjinpeng Industrial Co.,LTD

地址：深圳市南山区月亮湾大道 2076 号高科大厦六层 C3

Address: Room C3, 6/F Gaoke Building, No.2076, Yueliangwan BLVD,
Nanshan District, Shenzhen.

电话/TEL: 0755-86274981/26440278

URL: <http://www.cjpsz.com> E-mail: cjpsz126@126.com