



# NONDESTRUCTIVE TESTING REPORT

## Maintenance of HZ26-1 Platform CH185 Crane Winch

批准人 Approved by : 



URL: <http://www.cjpsz.com> E-mail: [cjpsz126@126.com](mailto:cjpsz126@126.com)

# 磁 粉 检 测 报 告

## MAGNETIC PARTICLE INSPECTION REPORT

项目名称: 维修HZ26-1平台CH185吊臂绞车

报告日期

报告编号:

Project :Maintenance of HZ26-1 Platform CH185 Crane Winch

Report Date: 2019.08.29

Report No. :CJP-WR-051-360-MT001-19-062


[illegible]



检测报告附图  
SKETCH OF DETECTION POSITION

报告编号:

Report No: CJP-WR-051-360-MT001-19-062



CH185A-36120-01-1

9606097



备注

Remark

1. 报告无检测单位“检测专用章”无效。  
Report without the specified inspection stamp of CJP company is invalid.
2. 报告无操作人员或评片人、技术监督、技术负责人签字无效。  
Report without the signatures of operator of film judge, tech. supervisor and tech. principal is invalid.
3. 本报告涂改无效。  
Report with alteration will be invalid.
4. 本报告仅对被检产品受检部位负责。  
Report is only responsible for the inspective pieces.
5. 未经检测单位同意不得复制本报告。  
Report should not be copied without the agreement of CJP company.
6. 委托单位对检测结果若有异议，请于十五日内提出。  
Client should inform CJP company within 15 days if there're any question about the inspective result.
7. 本报告一式三份；本公司存档一份，客户两份。  
Report is in triplicity, original stored in CJP company, two copies for client.
8. 未加盖 CMA 章的检测报告，不具备向社会起证明作用的数据和结果。  
The data and result of the inspection report that unsealed can not be proved to society.

检测单位：深圳市诚锦鹏实业有限公司

Contractor: Shenzhen Chengjinpeng Industrial Co.,LTD

地址：深圳市南山区月亮湾大道 2076 号高科大厦 6 层 C3

Address: Room C3, 6/F Gaoke Building, No.2076, Yueliangwan BLVD,  
Nanshan District, Shenzhen.

电话/TEL: 0755-86274981/26440278

URL: <http://www.cjpsz.com> E-mail: [cjpsz126@126.com](mailto:cjpsz126@126.com)