



深圳市诚锦鹏实业有限公司
SHENZHEN CHENGJINPENG INDUSTRIAL CO., LTD

无损检测报告

NONDESTRUCTIVE TESTING REPORT

工程名称 Project Name: HYSY291 四号辅机预润滑泵电机等维修-登船梯修复

HYSY291 No. 4 Auxiliary Machine Pre-Lubricating Pump Motor

and Other Repairs - Boarding Escalator Repair

委托单位 Commission Unit : 青岛太平洋海洋工程(深圳)有限公司

委托单位地址 Client Address: 宝安区松岗街道罗田社区龙山二路1号

工程编号 Project No. : CJP-WR-051-313-18-033


检测方法 Inspection Method : PT

报告编号 Report No. : CJP-WR-051-313-PT001-18-033

页数 Number of pages : 5

报告日期 Report Date : 2018.05.14

批准人 Approved by : [Signature]



检测单位: 深圳市诚锦鹏实业有限公司

CONTRACTOR: SHENZHEN CHENGJINPENG INDUSTRIAL CO.,LTD

地址: 深圳市南山区月亮湾大道 2076 号高科大厦 6FC3

ADDRESS: C3F6, GAOKE BUILDING, NO.2076, YUELIANGWAN BLVD, NANSHAN DISTRICT, SHENZHEN

电话 Tel: 0755-86274981/26440278

URL: <http://www.cjpsz.com> E-mail: cjpsz126@126.com

液体渗透检测报告

LIQUID PENETRANT INSPECTION REPORT

项目名称:HYSY291四号辅机预润滑泵电机等维修-登船梯修复

报告日期

报告编号

Project Name: HYSY291 No. 4 Auxiliary Machine Pre-Lubricating Pump Motor and Other Repairs - Boarding Escalator Repair

Report Date:2018.05.14

Report No. : CJP-WR-051-313-PT001-18-033

[illegible]

检测报告附图
SKETCH OF DETECTION POSITION

报告编号:

Report No: CJP-WR-051-313-PT001-18-033



001



002



003



004



005



006



检测报告附图
SKETCH OF DETECTION POSITION

报告编号:

Report No: CJP-WR-051-313-PT001-18-033



整体图



备注

Remark

1. 报告无检测单位“检测专用章”无效。
Report without the specified inspection stamp of CJP company is invalid.
2. 报告无操作人员或评片人、技术监督、技术负责人签字无效。
Report without the signatures of operator of film judge, tech. supervisor and tech. principal is invalid.
3. 本报告涂改无效。
Report with alteration will be invalid.
4. 本报告仅对被检产品受检部位负责。
Report is only responsible for the inspective pieces.
5. 未经检测单位同意不得复制本报告。
Report should not be copied without the agreement of CJP company.
6. 委托单位对检测结果若有异议，请于十五日内提出。
Client should inform CJP company within 15 days if there're any question about the inspective result.
7. 本报告一式三份；本公司存档一份，客户两份。
Report is in triplicity, original stored in CJP company, two copies for client.
8. 未加盖 CMA 章的检测报告，不具备向社会起证明作用的数据和结果。
The data and result of the inspection report that unsealed can not be proved to society.

检测单位：深圳市诚锦鹏实业有限公司

Contractor: Shenzhen Chengjinpeng Industrial Co.,LTD

地址：深圳市南山区月亮湾大道 2076 号高科大厦 6 层 C3

Address: Room C3, 6/F Gaoke Building, No.2076, Yueliangwan BLVD,
Nanshan District, Shenzhen.

电话/TEL: 0755-86274981/26440278

URL: <http://www.cjpsz.com> E-mail: cjpsz126@126.com