



深圳市诚锦鹏实业有限公司
SHENZHEN CHENGJINPENG INDUSTRIAL CO., LTD

无损检测报告

NONDESTRUCTIVE TESTING REPORT

工程名称 Project Name: 南海六号 1#伸缩节支撑环修理

Maintenance for Support Ring 1# Expansion Joints on NH6 Platform

委托单位 Commission Unit : 深圳市任俊锋实业有限公司

委托单位地址 Client Address: 惠州市惠阳区淡水镇行诚工业区

工程编号 Project No. : CJP-WR-083-120- 18-001

检测方法 Inspection Method : MT

报告编号 Report No. : CJP-WR-083-120-MT001-18-001

页数 Number of pages : 共 4 页

报告日期 Report Date : 2018.01.10

批准人 Approved by : _____



检测单位: 深圳市诚锦鹏实业有限公司

CONTRACTOR: SHENZHEN CHENGJINPENG INDUSTRIAL CO.,LTD

地 址: 深圳市南山区月亮湾大道 2076 号高科大厦 6FC3

ADDRESS: C3F6, GAOKE BUILDING, NO.2076, YUELIANGWAN BLVD, NANSHAN DISTRICT, SHENZHEN

电 话 Tel: 0755-86274981/86274982 传 真 Fax: 0755-26440269

URL: <http://www.cjpsz.com> E-mail: cjpsz@21cn.com



磁粉检测报告
MAGNETIC PARTICLE INSPECTION REPORT

项目名称: 南海六号1#伸缩节支撑环修理

报告日期	报告编号
2019年12月31日	2019-12-31-001
2020年1月15日	2020-01-15-002
2020年2月28日	2020-02-28-003
2020年3月31日	2020-03-31-004
2020年4月15日	2020-04-15-005
2020年5月31日	2020-05-31-006
2020年6月15日	2020-06-15-007
2020年7月31日	2020-07-31-008
2020年8月15日	2020-08-15-009
2020年9月30日	2020-09-30-010
2020年10月15日	2020-10-15-011
2020年11月30日	2020-11-30-012
2020年12月15日	2020-12-15-013
2021年1月31日	2021-01-31-014
2021年2月15日	2021-02-15-015
2021年3月31日	2021-03-31-016
2021年4月15日	2021-04-15-017
2021年5月31日	2021-05-31-018
2021年6月15日	2021-06-15-019
2021年7月31日	2021-07-31-020
2021年8月15日	2021-08-15-021
2021年9月30日	2021-09-30-022
2021年10月15日	2021-10-15-023
2021年11月30日	2021-11-30-024
2021年12月15日	2021-12-15-025
2022年1月31日	2022-01-31-026
2022年2月15日	2022-02-15-027
2022年3月31日	2022-03-31-028
2022年4月15日	2022-04-15-029
2022年5月31日	2022-05-31-030
2022年6月15日	2022-06-15-031
2022年7月31日	2022-07-31-032
2022年8月15日	2022-08-15-033
2022年9月30日	2022-09-30-034
2022年10月15日	2022-10-15-035
2022年11月30日	2022-11-30-036
2022年12月15日	2022-12-15-037
2023年1月31日	2023-01-31-038
2023年2月15日	2023-02-15-039
2023年3月31日	2023-03-31-040
2023年4月15日	2023-04-15-041
2023年5月31日	2023-05-31-042
2023年6月15日	2023-06-15-043
2023年7月31日	2023-07-31-044
2023年8月15日	2023-08-15-045
2023年9月30日	2023-09-30-046
2023年10月15日	2023-10-15-047
2023年11月30日	2023-11-30-048
2023年12月15日	2023-12-15-049
2024年1月31日	2024-01-31-050
2024年2月15日	2024-02-15-051
2024年3月31日	2024-03-31-052
2024年4月15日	2024-04-15-053
2024年5月31日	2024-05-31-054
2024年6月15日	2024-06-15-055
2024年7月31日	2024-07-31-056
2024年8月15日	2024-08-15-057
2024年9月30日	2024-09-30-058
2024年10月15日	2024-10-15-059
2024年11月30日	2024-11-30-060
2024年12月15日	2024-12-15-061
2025年1月31日	2025-01-31-062
2025年2月15日	2025-02-15-063
2025年3月31日	2025-03-31-064
2025年4月15日	2025-04-15-065
2025年5月31日	2025-05-31-066
2025年6月15日	2025-06-15-067
2025年7月31日	2025-07-31-068
2025年8月15日	2025-08-15-069
2025年9月30日	2025-09-30-070
2025年10月15日	2025-10-15-071
2025年11月30日	2025-11-30-072
2025年12月15日	2025-12-15-073
2026年1月31日	2026-01-31-074
2026年2月15日	2026-02-15-075
2026年3月31日	2026-03-31-076
2026年4月15日	2026-04-15-077
2026年5月31日	2026-05-31-078
2026年6月15日	2026-06-15-079
2026年7月31日	2026-07-31-080
2026年8月15日	2026-08-15-081
2026年9月30日	2026-09-30-082
2026年10月15日	2026-10-15-083
2026年11月30日	2026-11-30-084
2026年12月15日	2026-12-15-085
2027年1月31日	2027-01-31-086
2027年2月15日	2027-02-15-087
2027年3月31日	2027-03-31-088
2027年4月15日	2027-04-15-089
2027年5月31日	2027-05-31-090
2027年6月15日	2027-06-15-091
2027年7月31日	2027-07-31-092
2027年8月15日	2027-08-15-093
2027年9月30日	2027-09-30-094</

项目名称: 南海六号1#伸缩节支撑环修理	报告日期	报告编号
Project Name: Maintenance for Support Ring of 1# Expansion Joints on NH6 Platform	Report Date: 2018. 01. 10	Report No.: CJP-WR-083-1 20-MT001-18-001

[illegible]




Form No. :CJP/WR.MT01 Rev:E/0



检验报告附图
SKETCH OF DETECTION POSITION

报告编号:

Report: CJP-WR-083-120-MT001-18-001



南海 6#-1# 支撑环



备注

Remark

1. 报告无检测单位“检测专用章”无效。

Report without the specified inspection stamp of CJP company is invalid.

2. 报告无操作人员或评片人、技术监督、技术负责人签字无效。

Report without the signatures of operator of film judge, tech. supervisor and tech. principal is invalid.

3. 本报告涂改无效。

Report with alteration will be invalid.

4. 本报告仅对被检产品受检部位负责。

Report is only responsible for the inspective pieces.

5. 未经检测单位同意不得复制本报告。

Report should not be copied without the agreement of CJP company.

6. 委托单位对检测结果若有异议，请于十五日内提出。

Client should inform CJP company within 15 days if there're any question about the inspective result.

7. 本报告一式三份；本公司存档一份，客户两份。

Report is in triplicity, original stored in CJP company, two copies for client.

8. 未加盖 CMA 章的检测报告，不具备向社会起证明作用的数据和结果。

The data and result of the inspection report that unsealed can not be proved to society.

检测单位：深圳市诚锦鹏实业有限公司

Contractor: Shenzhen Chengjinpeng Industrial Co.,LTD

地址：深圳市南山区月亮湾大道 2076 号高科大厦 6 层 C3

Address: Room C3, 6/F Gaoke Building, No.2076, Yueliangwan BLVD,
Nanshan District, Shenzhen.

电话/TEL: 0755-86274981/26440278

URL: <http://www.cjpsz.com> E-mail: cjpsz126@126.com