



深圳市诚锦鹏实业有限公司
SHENZHEN CHENGJINPENG INDUSTRIAL CO., LTD

无损检测报告

NONDESTRUCTIVE TESTING REPORT

工程名称 Project Name: 南海五号隔水管连接器修理

Riser Connector Repair on NH5

委托单位 Commission Unit : 深圳市任俊锋实业有限公司

委托单位地址 Client Address: 惠州市惠阳区淡水镇新桥村

工程编号 Project No. : CJP-WR-083-137-18-050

检测方法 Inspection Method : UTT

报告编号 Report No. : CJP-WR-083-137-UTT001-18-050

页数 Number of pages : 共 4 页

报告日期 Report Date : 2018.08.21

批准人 Approved by :



检测单位: 深圳市诚锦鹏实业有限公司

CONTRACTOR: SHENZHEN CHENGJINPENG INDUSTRIAL CO.,LTD

地 址: 深圳市南山区月亮湾大道 2076 号高科大厦 6FC3

ADDRESS: C3F6, GAOKE BUILDING, NO.2076, YUELIANGWAN BLVD, NANSHAN DISTRICT, SHENZHEN

电 话 Tel: 0755-86274981/26440278

URL: <http://www.cjpsz.com> E-mail: cjpsz126@126.com



项目名称: 南海五号水管连接器修理

报告日期:

报告编号

Project Name:Riser Connector Repair On NH5

Report Date:2018.08.21

Report No: CJP-WR-083-137-UTT001-18-050

结构名称 Structure Name	南海五号三缸泵泵头	参考标准 Reference Criteria	GB/T11344-2008	对比试块 Reference Block	58mm厚铜合金
检测地点 Testing Position	任俊锋惠州库房	仪器型号 Instrument Type	CYGNUS 2	表面温度 Surface Temperature	21°
检测比例 Testing Rate	抽检	制造编号 Manufacture No.	CJP-CH-06	表面状态 Surface Condition	光滑
工件材质 Workpiece Material	铜合金	声速设定 Sound Velocity Settings	5919m/s	耦合剂 Couplant	化学浆糊 Chemical Paste

签字授权人(Authorized Sign)
Tang Yuezun
2018.08.22
1 页 共 1 页 Page

检验员 (Inspector)

技术监督(Tech. Supervisor)

签字授权人(Authorized Signee)

签字 Sign

zhaojie

Tang Yuezun

Tang Yezu

日期 Date

2018.08.27

2018.08.22

2018.08.22

检验报告附图
SKETCH OF DETECTION POSITION

报告编号:

Report No: CJP-WR-083-137-UTT001-18-050



CH-3

CH-2

CH-1



备注

Remark

1. 报告无检测单位“检测专用章”无效。
Report without the specified inspection stamp of CJP company is invalid.
2. 报告无操作人员或评片人、技术监督、技术负责人签字无效。
Report without the signatures of operator of film judge, tech. supervisor and tech. principal is invalid.
3. 本报告涂改无效。
Report with alteration will be invalid.
4. 本报告仅对被检产品受检部位负责。
Report is only responsible for the inspective pieces.
5. 未经检测单位同意不得复制本报告。
Report should not be copied without the agreement of CJP company.
6. 委托单位对检测结果若有异议，请于十五日内提出。
Client should inform CJP company within 15 days if there're any question about the inspective result.
7. 本报告一式三份；本公司存档一份，客户两份。
Report is in triplicity, original stored in CJP company, two copies for client.
8. 未加盖 CMA 章的检测报告，不具备向社会起证明作用的数据和结果。
The data and result of the inspection report that unsealed can not be proved to society.

检测单位：深圳市诚锦鹏实业有限公司

Contractor: Shenzhen Chengjinpeng Industrial Co.,LTD

地址：深圳市南山区月亮湾大道 2076 号高科大厦 6 层 C3

Address: Room C3, 6/F Gaoke Building, No.2076, Yueliangwan BLVD,
Nanshan District, Shenzhen.

电话/TEL: 0755-86274981/26440278

URL: <http://www.cjpsz.com> E-mail: cjpsz126@126.com